

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218



Policy # 6308271183

Ins Claim # F300301218



138

Kitchen Cabinets



139

Kitchen

Photo No. 41

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218
Policy # 6308271183
Ins Claim # F300301218



140

Kitchen

PITTSBURGH
MAY 07 2003
Ans. _____



141

Studio

Photo No. 42

Photo Sheet

Case 1:04-cv-00175-SJM

Document 23-4

Filed 12/16/2005

Page 3 of 20

Coverage BLDG

Claim #

F300301218

Policy #

6308271183

Ins Claim #


F300301218

Insured Borden, Jonathan



144

Studio



145

Studio Bedroom

Photo No. 43

Photo Sheet


Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



146

Studio Bedroom



147

Windows in studio bedroom

Photo No. 44

Photo Sheet

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



148

Studio bedroom



149

Stairwell down from studio to
kitchen area

Photo No. 45

Photo Sheet

Coverage BLDG


Insured Borden, Jonathan

Claim # F300301218
Policy # 6308271183
Ins Claim # F300301218



152

Garage



153

Garage

Photo No. 46

Case 1:04-cv-00175-SJM Document 23-4 Filed 12/16/2005 Page 7 of 20

Photo Sheet

Insured Borden, Jonathan


Coverage BLDG

Claim # F300301218
Policy # 6308271183
Ins Claim # F300301218



154

Garage rear wall



155

Garage

Photo No. 47

Photo Sheet

Insured Borden, Jonathan


Coverage BLDG

Claim # F300301218
Policy # 6308271183
Ins Claim # F300301218



156

Garage rear wall framing



157

Garage

Photo No. 48

Photo Sheet

Case 1:04-cv-00175-SJM

Document 23-4

Filed 12/16/2005

Page 9 of 20


Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



158

Hallway floor next to kitchen and garage



159

Hallway pantry area adjacent to the kitchen

Photo No. 49

Photo Sheet

Insured Borden, Jonathan

Coverage BLDG


Claim # F300301218

Policy # 6308271183

Ins Claim # F300301218



160

Pantry located in area between
kitchen and garage

161

Hallway/Pantry area

Photo No. 50

Photo Sheet


Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218


Policy # 6308271183

Ins Claim # F300301218



162

Hallway between kitchen and garage



163

Closet in hallway area between
garage and kitchen

Photo No. 51

Photo Sheet

Coverage BLDG

Claim # F300301218

Policy # 6308271183


Ins Claim # F300301218

Insured Borden, Jonathan



164

Basement



165

Basement

Photo No. 52

Photo Sheet

Insured Borden, Jonathan


Coverage BLDG

Claim # F300301218
Policy # 6308271183
Ins Claim # F300301218



166

Basement



167

Basement

Photo No. 53

Photo Sheet

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218

Policy # 6308271183

Ins Claim # F300301218

172

Basement



MAY 07 2003
Ans. _____

173

Trash incinerator in basement




Photo No. 54

Photo Sheet


Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218



Policy # 6308271183

Ins Claim # F300301218



176

Laundry sink in basement



177

Floor joists under formal dining area
from basement crawl space opening

Photo No. 55

Photo Sheet

Insured Borden, Jonathan

Coverage BLDG

Claim # F300301218

Policy # 6308271183

Ins Claim # F300301218

178

Basement from fallen flooring in den



MAY 07 2003
Am

Photo No. 56




Photo No. 57



Photo No. 58




Photo No. 59



Photo No. 60